






RECCOMENDED TEMPERATURE RANGE CHART FOR PACKAGING MATERIALS

-40°F 400°F

	RECYCLE#	BLAST FREEZER	FREEZER	CHILLED/ REFRIGERATED	ROOM TEMP	HEATED DISPLAY	MICROWAVE	OVEN
PP (POLYPROPELYENE)			0°F	←			→	250°
ALUMINUM	N/A	-20°	←				→	400°
PAPERBOARD	N/A	-40°	←				→	400°
OPS (POLYSTYRENE)			20°	←			→	180°
PS FOAM			0°	←			→	150°
PET		-20°	←				→	120°
HIPS			0°	←			→	180°
MOLDED FIBER	N/A		FREEZER	←		→	MICROWAVE REHEAT ONLY	

